





FIG. 1



08/795708-020497

264020-80/56/80





264020 80256280

FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10





FIG. 11



08795708.020497

FIG. 13




FIG. 12




FIG. 17




FIG. 19




FIG. 14




FIG. 15




FIG. 18





FIG. 16



08795708-0204-97

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		


61534 U.S. PTO

08/795708



02/04/97

FIG. 20



08795708-020497

464020" 80456480

FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 32





FIG. 31



APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

61534 U.S. PTO
08/795708
02/04/97




FIG. 25




FIG. 26




FIG. 27




FIG. 28

08795708-020497

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

61534 U.S. PTO

08/795708



02/04/97






FIG. 35





FIG. 34

08795708-020497

464020" 80256280

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

61534 U.S. PTO
08/795708
02/04/97







FIG. 42




FIG. 43




FIG. 41




FIG. 44





FIG. 40



APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

61534 U.S. PTO
08/795708
02/04/97

